

Tandler Gearbox Retrofit


TIP Z024-0001

Gravure Print Decks


Benefits:

- This improvement replaces obsolete gearboxes with commercially available units.

Safety	<input type="text"/>
Obsolescence	<input type="text"/>
Quality	<input type="text"/>
Cost Reduction	<input type="text"/>
Performance	<input type="text"/>
Maintenance	<input type="text"/>



Revised Design



Original Design

Tandler Gearbox Retrofit

Machine Model for Improvement: Zerand Gravure Print Decks

Description of Improvement:

This improvement replaces the existing obsolete gearboxes with new commercially available Tandler gearboxes.

This improvement includes new torque tubes, couplings and mounts for the gearboxes.

Tandler Gearbox Retrofit

Included in this TIP:

- All required parts
- Necessary engineering
- Updated documentation pages for relevant sections

Estimated downtime, no production:

- 10 days

Estimated startup, limited production:

- 3 day

Estimated monitoring in production:

- 3 day

Required manpower:

- 1 BW Papersystems Mechanical Field Service Engineer
- 1 BW Papersystems Electrical Engineer
- Additional Assistance from Customers' Maintenance

(Additional local resources to be determined, if needed)

How can we help you? Please do not hesitate to contact us for any questions regarding our comprehensive Customer Service offerings:

TIPs/Upgrades:

- tips.zerand@bwpapersystems.com

Spare Parts:

- zerandparts@bwpapersystems.com

Service Requests:

- zerandservice@bwpapersystems.com

In case of emergency please contact our hotline 24 hours a day:

NORTH AMERICA +1 262 827 3800

Please note: these statements are for general information only and are subject to change without prior notice. We would be pleased to send you a detailed offer, following an inspection of your machine.

07/2019

BWP Zerand
15800 W. Overland Drive
New Berlin, WI 53151

t. +1-262-827-3800
zerand.com
bwpapersystems.com

barrywehmiller
bw
betterworld